



Firmware for DJM-900NXS2 – CHANGE HISTORY

ver. 2.07 (26 March, 2020 Update)

[IMPROVED]

- ✓ More functions are now supported by TC Supply ShowKontrol.

ver. 2.06 (14 January, 2020 Update)

[FIXED]

- ✓ When used with DJM-REC, sometimes recording or live streaming stopped.

ver. 2.05 (19 December, 2017 Update)

[FIXED]

- ✓ Incorrect audio input/output signal was sent when connecting to an iOS device.
- ✓ When connecting to an iOS device, connections with the iOS device and the effect channel selector switch did not work.

ver. 2.03 (12 October, 2017 Update)

[NEW]

- ✓ Support for TC Supply ShowKontrol software.

ver. 2.02 (8 August, 2017 Update)

[IMPROVED]

- ✓ Cut lag length improved for a more responsive scratch performance.

[FIXED]

- ✓ Popping noise occurred via USB audio (FX SEND/RETURN) when switching FX assign on rekordbox with BEAT FX enabled.
- ✓ Fixed other minor issues.

ver. 2.01 (14 February, 2017 Update)

[FIXED]

- ✓ More precise cut lag value on both edges of the crossfader.
- ✓ PRO DJ LINK: The CDJ display froze when connecting to another computer while controlling DJ software from the CDJ using HID control.

- ✓ Small popping noise occurred when turning the EQ/ISO knob when ISOLATOR was selected for EQ CURVE.

ver. 2.00 (25 October, 2016 Update)

[IMPROVED]

- ✓ Sound quality enhanced by improving internal digital signal dithering process (DSP). AUTO, TAP and BEAT found on the main display visually improved.

[FIXED]

- ✓ Incorrect audio output when changing Beat FX or FX channels.
- ✓ Channel level indicator was lit when launching.
- ✓ Switching noise occurred when changing USB Output Level.

ver. 1.20 (2 August, 2016 Update)

[NEW]

- ✓ KUVO real-time information distribution is available when tracks are played on rekordbox dj (Ver.4.2.1.).

[FIXED]

- ✓ Clicking noise occurred when using FILTER of SOUND COLOR FX.
- ✓ Pop noise occurred when launched from DIGITAL MASTER OUT.
- ✓ Improved stability and fixed minor issues.

[IMPROVED]

- ✓ Response of SOUND COLOR FX buttons and faders.

ver. 1.10 (23 May, 2016 Update)

[FIXED]

- ✓ SOUND COLOR FX worked incorrectly.
- ✓ Input volume decreased when FLANGER was selected using LEVEL/DEPTH knob.
- ✓ PRO DJ LINK worked incorrectly.

[IMPROVED]

- ✓ SOUND COLOR FX curve for HPF.

ver. 1.09 (10 February, 2016 Update)

[FIXED]

- ✓ Audio dropouts occurred in certain conditions when DIGITAL was selected from the INPUT selector knob.

ver. 1.07 (28 January, 2016 Update)

[FIXED]

- ✓ Dependent on hardware, certain PRO DJ LINK features worked incorrectly due to network issues.
- ✓ NOISE and SWEEP of SOUND COLOR FX applied before BEAT FX, not after BEAT FX (same as DJM-900NXS).
- ✓ Noise may occur when turning the COLOR knob for DUB ECHO in SOUND COLOR FX.
- ✓ GAIN of USB SND/RTN.
- ✓ Switching noise occurred when sampling rate of Digital Out changed.
- ✓ MIDI code bug.
- ✓ USB SND/RTN hung up when buffer size of iOS application was switched at a high speed.
- ✓ Other minor issues.

[IMPROVED]

- ✓ SOUND COLOR FX
 - NOISE: VOLUME when PARAMETER is MAX.
 - DUB ECHO: Echo sound remains (not attenuated) when PARAMETER is MAX (regardless of knob position of the assigned deck).
 - FILTER: Resonance decreased when PARAMETER for [LPF/HPF] is MIN.
Effect changes more smoothly at the beginning of turning the knob for HPF.
- ✓ Acceleration of the TIME knob.

