



Firmware for RMX-1000 – CHANGE HISTORY

Ver.2.20 (27 November, 2018 Update)

- ✓ Improved stability.

Ver.2.11 (10 June, 2013 Update)

- ✓ Fixed a rare issue where no sound would be output when ECHO is selected from SCENE FX.

Ver.2.10 (7 February, 2013 Update)

- ✓ Fixed an issue where the output audio level is lowered when using REMIX-STATION 500 as USB audio interface.

Ver.2.01 (29 November, 2012 Update)

- ✓ In line with the firmware update of RMX-1000 Plug-in, the MIDI button type names and the MIDI messages are changed. Please refer to "Important notice to those who have purchased an REMIX-STATION 1000" for further details.

Ver.1.31 (25 July, 2012 Update)

- ✓ BPM percent increase and decrease by pressing the [NUDGE (+, -)] button is shown in the [BPM] display on both remixbox and REMIX-STATION 1000.
- ✓ The response of some buttons of ISOLATE FX and SCENE FX has been improved.
- ✓ Fixed issue where the volume of SPIRAL UP/DOWN (SCENE FX) got excessively loud.
- ✓ Improved the sound when BACK SPIN (RELEASE FX) was about to disappear.
- ✓ Fixed the issue of QUANTIZE when it was used with OVERDUB (X-PAD FX).
- ✓ Lifted the upper limit of beats in LOOP mode when X-PAD FX is used.

The maximum length of the sampled sound that can be stored in a BANK (Total of 4 SLOTS) stays the same at 16 seconds.

Ver.1.20 (24 May, 2012 Update)

- ✓ Fixed an issue that a user may rarely hear slight noise on the output sound.

Ver.1.19 (25 April, 2012 Update)

- ✓ The problems in sending and receiving MIDI signals with the plug-in have been corrected.
- ✓ The illumination of the X-PAD FX section during use of the RELEASE FX switch has been partially modified.