



Firmware for DJM-900NXS2 – CHANGE HISTORY

Ver.1.10 (23 May, 2016 Update)

[FIXED]

- ✓ SOUND COLOR FX worked incorrectly.
- ✓ Input volume decreased when FLANGER was selected using LEVEL/DEPTH knob.
- ✓ PRO DJ LINK worked incorrectly.

[IMPROVED]

- ✓ SOUND COLOR FX curve for HPF.

Ver.1.09 (10 February, 2016 Update)

[FIXED]

- ✓ Audio dropouts occurred in certain conditions when DIGITAL was selected from the INPUT selector knob.

Ver.1.07 (28 January, 2016 Update)

[FIXED]

- ✓ Dependent on hardware, certain PRO DJ LINK features worked incorrectly due to network issues.
- ✓ NOISE and SWEEP of SOUND COLOR FX applied before BEAT FX, not after BEAT FX (same as DJM-900NXS).
- ✓ Noise may occur when turning the COLOR knob for DUB ECHO in SOUND COLOR FX.
- ✓ GAIN of USB SND/RTN.
- ✓ Switching noise occurred when sampling rate of Digital Out changed.
- ✓ MIDI code bug.
- ✓ USB SND/RTN hung up when buffer size of iOS application was switched at a high speed.
- ✓ Other minor issues.

[IMPROVED]

- ✓ SOUND COLOR FX
 - NOISE: VOLUME when PARAMETER is MAX.
 - DUB ECHO: Echo sound remains (not attenuated) when PARAMETER is MAX (regardless of knob position of the assigned deck).
 - FILTER: Resonance decreased when PARAMETER for [LPF/HPF] is MIN.
Effect changes more smoothly at the beginning of turning the knob for HPF.
- ✓ Acceleration of the TIME knob.