Pioneer Dj

macOS High Sierra 10.13 driver install issue

macOS High Sierra 10.13 introduces a new security feature that requires user approval before installing pioneer DJ 's new driver software described as below.


(Note: this does not affect drivers that were already installed before updating to macOS High Sierra 10.13)

When installing pioneer DJ 's driver software for the first time on macOS High Sierra 10.13, a pop-up like the screen shot below will appear.



When you see a "System Extension Blocked" message (screen shot above), please click "OK". You will then need to allow the driver install process to complete. Please follow the instructions below.

1. Open "System Preferences" and click "Security & Privacy".



Pioneer Dj

2. When the "Security & Privacy" opens, you will see a message below:

System software from developer "Pioneer DJ Corporation" was blocked from loading. This message is present in the "Security & Privacy" for only 30 minutes after starting driver installation. When this message does not appear, please install the driver software again

3. Click "Allow".

| | Security & Privacy | Q Search |
|---|-----------------------------------|--------------------|
| Gene | ral FileVault Firewall Priva | су |
| | | |
| A login password has been set for this user Change Password | | |
| 🗹 Require password | immediately ᅌ after sleep or so | creen saver begins |
| Show a message when the screen is locked Set Lock Message | | |
| ✓ Disable automatic login | | |
| | | |
| | | |
| | | |
| Allow apps downloaded fr | om: | |
| O App Store | | |
| App Store and ider | ntified developers | |
| | | |
| | | |
| System software from dev blocked from loading. | eloper "Pioneer DJ Corporation" w | Allow |
| L | | |
| | | |
| \bigcirc | | |
| Click the lock to make change | es. | Advanced ? |
| | | |

4. When your hardware is connected to your Mac, disconnect and re-connect the hardware.

This issue only affects new drivers installed after updating to macOS High Sierra 10.13. If you have installed drivers for your hardware on a previously macOS or OS X version, you will not run into this issue.



The DJ equipment that requires the above procedure when installing the driver software are as follows:

| DJ MIXER DJM-TOUR1 DJM-2000NXS | ALL-IN-ONE DJ SYSTEM XDJ-RX2 XDJ-RX |
|--------------------------------------|---|
| DJM-2000 DJM-900NXS2 | XDJ-AERO |
| DJM-900NXS | AUDIO INTERFACES |
| DJM-900SRT | INTERFACE2 |
| DJM-850 | |
| DJM-750MK2 | REMIX STATION |
| DJM-750 | RMX-500 |
| DJM-450 | |
| DJM-250MK2 | DJ PLAYER |
| DJM-S9 | MEP-7000 |
| DJM-S3 | |
| DJM-T1 | |
| DJM-5000 | |
| | |

DJ CONTROLLER

DDJ-1000 DDJ-RZX DDJ-RZ DDJ-RR DDJ-RB DDJ-SZ2 DDJ-SZ DDJ-SR2

About Trademarks and Registered Trademarks

- Pioneer DJ is a trademark of the PIONEER CORPORATION and is used under license.
- Mac, OS X and macOS are registered trademarks of Apple Inc. in the U.S. and other countries.

© 2018 Pioneer DJ Corporation. All rights reserved.

PIONEER DJ CORPORATION

6F, Yokohama i-Mark Place, 4-4-5 Minatomirai, Nishi-ku, Yokohama, Kanagawa 220-0012 Japan

Version 1.01