Windows Firmware for DJM-S9 – CHANGE HISTORY

Ver.1.06 (21 December, 2015 Update)
[FIXED]
- ✓ Incorrect MIDI value when using crossfader.
- ✓ Pressing PADs repeatedly in FX TRIGGER MODE with effect lever held in LOCK leaked original sound.
- ✓ BPM of channel 1/2 BEAT FX was sometimes different from the displayed BPM with SAMPLER FX or AUX FX engaged.
- ✓ Other minor issues.

Ver.1.05 (23 November, 2015 Update)
- ✓ IMPROVED - Cut lag length changed to 1 mm when the DJM-S9 is not connected to a computer.

Ver.1.04 (28 October, 2015 Update)
- ✓ Fixed an issue where the CLIP LED was not lit.
- ✓ Fixed an issue where AUX audio is not output when FADER SYNTH is selected from BEAT FX.
- ✓ Fixed an issue where NOISE effect may not be activated when it is switched from other effect of FILTER FX in the Setting Utilities.
- ✓ Fixed an issue where noise may be heard when closing Serato DJ while Serato DJ effects are still enabled.
- ✓ Fixed an issue where the UTILITY LED remains lit even after exiting the Utility mode.
- ✓ Improved the response when the effect lever is pulled down repeatedly.
- ✓ The audio level of SAMPLER is now at an appropriate level.
- ✓ Fixed other minor issues.