AlphaTheta

DDJ-FLX10 Firmware – Change History

ver. 1.13 (October 29, 2024 update)

[IMPROVED]

✓ Following the Eco-design Directive (Directive 2009/125/EC) of the European Union, the time needed for the unit to automatically switch off has been changed to 20 minutes when the Power Management function is turned on.

Please note:

➢ The name of the energy-saving function, (previously called Auto Standby or Auto Power-Off, depending on the model), has now been changed to Power Management.

➢ To learn more about the Power Management function, see the latest Instruction Manual, which is available online.

ver. 1.12 (April 25, 2023 update)

[IMPROVED]

✓ When using Part ISO mode, changing the layout settings of the Track Separation function in rekordbox now swaps the part to be adjusted with the EQ knob.

Note: Please be sure to update rekordbox to the latest version (ver. 6.7.1 or later).

ver. 1.11 (March 23, 2023 update)

[NEW]

✓ Serato DJ Pro is now supported.

✓ Changing the settings via Utilities mode is now supported.

[FIXED]

✓ Occasionally incorrect start of the DDJ-FLX10 after turning on the power.

✓ Other minor bugs have been fixed.