Pioneer DJ

CDJ-3000 firmware – Change History

ver. 3.00 (June 27, 2023 update)
[NEW]
- ✓ Support for StreamingDirectPlay for Beatport Streaming.

ver. 2.04 (February 28, 2023 update)
[NEW]
- ✓ Stagehand app compatibility added.

[FIXED]
- ✓ Occasionally BPM and key weren't reflected when using Track Filter.
- ✓ Occasionally Hot Cue worked incorrectly during loop.

ver. 2.03 (October 13, 2022 update)
[NEW]
- ✓ A total of up to 6 CDJ-3000 and DJS-1000 units can now be connected via PRO DJ LINK.
  * Please update the firmware of the CDJ-3000 and DJS-1000 to the latest versions.

[FIXED]
- ✓ Beat Countdown was displayed incorrectly.
- ✓ When scratching or using a Hot Cue on the master player with Beat Sync turned on, the tempo of other players would change.

ver. 2.02 (April 14, 2022 update)
[IMPROVED]
- ✓ Search speed.

[FIXED]
- ✓ Artwork was sometimes displayed in low resolution when loaded from a storage device (SD / USB) formatted with HFS+.
- ✓ Hot Cue colors were sometimes dsplayed incorrectly during rekordbox CloudDirectPlay.

ver. 2.01 (December 15, 2021 update)
[FIXED]
- ✓ PHASE METER was not shown correctly on the screen.

ver. 2.00 (November 30, 2021 update)

[NEW]

- ✓ Support for rekordbox CloudDirectPlay.

[IMPROVED]

- ✓ Hot Cue points weren't displayed on the waveform screen under certain conditions.

[FIXED]

- ✓ Some WAV files couldn't be played.
- ✓ The first decimal place of the BPM value was different from the previous model, the CDJ-2000NXS2.
- ✓ Hot Cue Loop function worked incorrectly under certain conditions.

ver. 1.22 (November 12, 2021 update)

[FIXED]

- ✓ Latency occurred during USB-HID control.
- ✓ PRO DJ LINK worked incorrectly when linked to an internet connection while using the CDJ-3000 firmware ver.1.21.

ver. 1.21 (October 12, 2021 update)

[FIXED]

- ✓ BPM sometimes displayed incorrectly when moving the tempo slider.

ver. 1.20 (September 30, 2021 update)

[NEW]

- ✓ HID Support for Serato DJ Pro.

[IMPROVED]

- ✓ Jog wheel pitch bend sensitivity.

[FIXED]

- ✓ Waveforms from the CDJ-3000 didn't show on the tilt displays of the CDJ-TOUR1 and DJM-TOUR1.

  Note: Update the CDJ-TOUR1/DJM-TOUR1 firmware to the latest version.

- ✓ Issues when deleting a track from a tag list.

ver. 1.11 (June 24, 2021 update)

[FIXED]

- ✓ Date Added was not shown correctly.
- ✓ Stacked waveform flickered when using some files.
- ✓ Beat Sync worked incorrectly when using some MP3 files.
- ✓ Some m4a files wouldn't play on the CDJ-3000

ver. 1.10 (April 22, 2021 update)

[NEW]

✓ Support for TC Supply's ShowKontrol and PRO DJ LINK Bridge.

ver. 1.09 (March 16, 2021 update)

[FIXED]

✓ Emergency Loop could start when the Hot Cue button was pressed during pause (using Pause or Cue).

ver. 1.08 (February 9, 2021 update)

[NEW]

✓ Audio file cache now supports a full file.

✓ Support for KUVO.

[FIXED]

✓ Incorrect key notation on the Load Previous Track screen.

ver. 1.06 (November 4, 2020 update)

[FIXED]

✓ Improved the response of the CUE button when turning the jog wheel.

✓ Improved performance / stability when using Touch Preview and Touch Cue.

✓ Improvements to jog wheel when in vinyl mode. Specifically when the track is paused.

✓ Unable to load certain tracks that have been exported from rekordbox to a storage device (SD / USB).

✓ Elements of the Beat Countdown were displayed incorrectly.

Ver.1.05 (September 16, 2020 Update)

[IMPROVED]

✓ Quality of enlarged waveform.