Firmware for CDJ-850 – CHANGE HISTORY

Ver.1.13 (6 September, 2018 Update)
[FIXED]
- ✓ Playback sometimes stopped when playing a track with a length over 10 minutes when using TRAKTOR via USB.
- ✓ Some USB 3.0 devices were not recognised.

Ver.1.12 (30 September, 2013 Update)
- ✓ Fixed an issue that the MIDI-data is not output to a particular computer.

Ver.1.08 (17 July, 2012 Update)
- ✓ Improved output accuracy of the time code signals in DVS operation using CONTROL CD.

Ver.1.06 (7 July, 2011 Update)
- ✓ Improved functionality so that user can switch the source between PC (COMPUTER) and DISC while DJ software is running.

Ver.1.04 (25 April, 2011 Update)
- ✓ Became accessible to some USB 2.0 compatible USB 3.0 media. The data rate to USB 3.0 media is limited to USB 2.0 full-speed.
- ✓ Improved the JOG touch feeling when using some DJ software.
- ✓ Auto Beat Loop is improved as accurate as CDJ-800mk2.