Pioneer DJ

Firmware for CDJ-900NXS – CHANGE HISTORY

Ver.1.31 (5 October, 2017 Update)
[FIXED]
- ✓ Track playback speed sometimes did not return to the BPM displayed on the screen when Sync is enabled.
- ✓ Fixed certain issues during playback and track selection.

Ver.1.30 (24 November, 2016 Update)
[NEW]
- ✓ MASTER PLAYER SELECT (AUTO) support (TORAIZ SP-16 PRO DJ LINK feature)
- ✓ Search using multiple words by adding a space in the [SEARCH] category.

[FIXED]
- ✓ When connected via Pro DJ LINK, some features of the CDJ-2000NXS2 or XDJ-1000MK2 were disabled.
- ✓ Playback of an AIFF music file (24bit/48kHz) stopped and tracks could not be loaded to a deck.
- ✓ Digitally distorted white noise occurred when playing certain .WAV files.
- ✓ Active loop activated a very short loop.
- ✓ macOS 10.12 Sierra: CDJ-900NXS was sometimes not recognized as an audio device.
- ✓ Fixed problems in the Control Mode.

Ver.1.22 (20 August, 2015 Update)
- ✓ Fixed an issue where some HDD may not be recognized when connected to a CDJ-900NXS.
- ✓ Fixed an issue where a noise may be heard when Master Tempo is activated.

Ver.1.21   (17 February, 2015 Update)
- ✓ Fixed an issue where tracks in some folders in a 2TB HDD were not displayed when browsing the folder.

- ✓ Fixed an issue of slow browsing in the track list on CDJ-900NXS when Serato DJ is used in HID mode.
- ✓ Fixed an issue where track selection using the alphabetical search is not available and the "waiting circle" is continuously shown.

Ver.1.20 (1 April, 2014 Update)
- ✓ Add a new function (analyzing a part of MP3/AIFF Tags) to support KUVO service.
  This update is only for using KUVO.
- ✓ Fixed an issue where playback sound stops while BEAT DIVIDE is activated.