# Windows Plug-in for RMX-1000 – CHANGE HISTORY

## Ver.2.1.2 (7 June, 2016 Update)
**[FIXED]**
- ✓ Plug-in software did not start correctly on Windows10.

## Ver.2.1.1 (10 June, 2013 Update)
- ✓ Fixed a rare issue where no sound would be output when ECHO is selected from SCENE FX.

## Ver.2.1.0 (7 February, 2013 Update)
- ✓ Ver.2.1.0 reflects REMIX-STATION 1000 Platinum Edition colour on the GUI.
- ✓ Fixed minor issues.

## Ver.2.0.0 (29 November, 2012 Update)
- ✓ The support of RTAS (Real-Time Audio Suite) format became available.
- ✓ A new body color of pearl white for the GUI of REMIX-STATION 1000-W became available.
- ✓ Fixed an issue where "automation" did not work when using some host applications.
- ✓ Changed the MIDI codes because of conflicts with some host applications in MIDI mappings.
- ✓ Deleted the MIDI Channel icon on the Plug-in.
- ✓ Added the LINK bottun for selecting the Plug-in controlled by REMIX-STATION 1000 when multiple Plug-ins are activated.
- ✓ The last status of Plug-in can be saved on the host applications.
- ✓ Improved an issue where audio glitching caused by processing would be heard on some host applications.

## Ver.1.0.0 -> Ver.1.1.0 (25 July, 2012 Update)
- ✓ BPM percent increase and decrease by pressing the [NUDGE (+, -)] button is shown in the [BPM] display on both remixbox and REMIX-STATION 1000.

- ✓ Fixed issue where recording of "automation" did not work when using some host applications as plug-in devices and controlling it by REMIX-STATION 1000.
- ✓ Fixed issue where the volume of SPIRAL UP/DOWN (SCENE FX) got excessively loud.
- ✓ Improved the sound when BACK SPIN (RELEASE FX) was about to disappear.
- ✓ Lifted the upper limit of beats in LOOP mode when X-PAD FX is used. The maximum length of the sampled sound that can be stored in a BANK (Total of 4 SLOTS) stays the same at 16 seconds.

## 25 April, 2012　　First Release