



Windows 10 Driver for RMX-500 – CHANGE HISTORY

Ver.1.010 (29 November, 2016 Release)

[FIXED]

- ✓ DJ applications running on certain versions of Windows 10 did not detect Pioneer DJ equipment.