



Windows Firmware for DDJ-1000 – CHANGE HISTORY

Ver.1.06 (19 February, 2019 Update)

[IMPROVED]

- ✓ The gap between the crossfader position of the DDJ-1000 and that of rekordbox.

[FIXED]

- ✓ Minor issues.

Ver.1.05 (26 June, 2018 Update) [FIXED]

- ✓ Error when pressing SHIFT and using the jog wheel.

Ver.1.04 (27 March, 2018 Update) [FIXED]

- ✓ Error when pressing SHIFT and using the jog wheel.

Ver.1.03 (22 January, 2018 Update) [FIXED]

- ✓ Jog dial display section flashed for a moment when the DDJ-1000 was powered on.
- ✓ The channel level indicator lit incorrectly when using NOISE in SOUND COLOR FX.
- ✓ The channel level indicator stopped when the DDJ-1000 was disconnected during playback with rekordbox connected to the USB terminal (USB A).
- ✓ Unable to turn on/off BEAT FX when using rekordbox.