



## **DDJ-1000SRT Firmware – CHANGE HISTORY**

**ver. 1.05 (9 March, 2021 Update)**

**[FIXED]**

- ✓ Minor issues have been fixed.

**ver. 1.02 (29 October, 2019 Update)**

**[FIXED]**

- ✓ The BPM values that are shown on the DDJ-1000SRT Beat FX display and in Serato DJ Pro virtual deck, did not sync.
- ✓ Sampler sound did not come out from the headphone output when the Sampler Cue button was pressed while the Sampler volume level was at its lowest.

The MIDI message for the Sampler VOL knob has been changed in line with this fix.