



Windows Firmware for DDJ-RB – CHANGE HISTORY

Ver.1.03 (14 February, 2017 Update)

- ✓ Sometimes hi-pitched noise occurred and the DDJ-RB hanged after using it for a long time.

Ver.1.02 (27 April, 2016 Update)

- ✓ Information of the following settings in the utility mode was not sent to rekordbox.
 - Mono/stereo switching of master output
 - Master output peak limiter
 - MIC output peak limiter
- ✓ Fixed an issue where BACKSPIN LENGTH does not work as expected.