



## Firmware for DDJ-SR – CHANGE HISTORY

### Ver.1.08 (24 February, 2016 Update)

#### [FIXED]

- ✓ Sound recorded by the DJ application was sometimes distorted (Clipping).
  - \* This problem did not happen in the following cases.  
When "MIX" was selected from the Input select dropdown menu in the Recording Panel of Serato DJ.  
(This is the default setting for recording.)  
If you select "MIX", you do not have to update the firmware to Ver.1.08.

### Ver. 1.07 (9 January, 2014 Update)

- ✓ Fixed an issue where a DJ application might not be controlled by the DDJ-SR when the TEMPO sliders on the DDJ-SR are moved.

### Ver. 1.06 (19 December, 2013 Update)

- ✓ Fixed an issue where the Key Lock function might be turned on and off unintentionally.

### Ver. 1.05 (26 November, 2013 Update)

- ✓ Improved the Trans Pad function.
- ✓ Improved the Combo FX function.
- ✓ Improved the accuracy and the function of tempo mode in Pad Plus mode.
- ✓ Improved the accuracy of FILTER control and EQ (HI, MID, LOW) controls.

### Ver. 1.02 (10 October, 2013 Release)

- ✓ Optimized the Velocity curve for Sampler Velocity mode.
- ✓ Improved the Trans Pad function.
- ✓ Fixed an issue where tracks' BPM values on DDJ-SR and Serato DJ sometimes may not synchronize in the Pad Plus mode.
- ✓ Fixed an issue where Filter works unintentionally when Pad4 or Pad8 is pressed in the Combo FX mode.
- ✓ Fixed an issue where some LEDs are turned off when a track is

loaded.