



## **Firmware for DDJ-SX – CHANGE HISTORY**

### **Ver.1.07 (13 May, 2013 Update)**

- ✓ Optimized the jog platter sensitivity where the touch sensor level knob is close to max.  
Please ensure the touch sensor level is adjusted to the appropriate level after updating the firmware.

### **Ver.1.05 (19 February, 2013 Update)**

- ✓ Improved the operability of the performance pads in the SAMPLER VELOCITY MODE.
- ✓ Reduced audio distortion which may occur with excessively large microphone input.

### **Ver.1.02 (4 December, 2012 Update)**

- ✓ Scratching became available when the VINYL mode is off and the track is paused.
- ✓ Fixed an issue when using generic MIDI control.

### **Ver.1.01 (1 November, 2012 Update)**

- ✓ Optimized the touch sensor sensitivity adjustment range for the jog dial.
- ✓ Fixed an issue when using generic MIDI control.