



Windows Firmware for RMX-500 – CHANGE HISTORY

Ver.1.08 (12 February, 2014 Update)

- ✓ Fixed an issue where the output audio level is lowered when using REMIX-STATION 500 as USB audio interface.
- ✓ Fixed an issue where REMIX-STATION 500 may not work as a plug-in controller depending on the computer used.