

RMX-500 – FIRMWARE CHANGE HISTORY

Ver 1.08

- ✓ Fixed an issue where the output audio level is lowered when using REMIX-STATION 500 as USB audio interface.
- ✓ Fixed an issue where REMIX-STATION 500 may not work as a plug-in controller depending on the computer used.