



Windows Firmware for DJM-2000 – CHANGE HISTORY

Ver.3.21 (10 July, 2018 Update)

[FIXED]

- ✓ Unable to record audio when using macOS10.13.2.

Ver.3.20 (16 October, 2013 Update)

- ✓ Supports "KUVO".

Ver.3.19 (30 May, 2013 Update)

- ✓ Fixed an issue where a buzzing noise may be heard when switching sampling rates on a DJ application while the USB soundcard of DJM-2000NXS is used.

Ver.3.18 (20 December, 2012 Update)

- ✓ Added BEAT SLICE REMIX.
- ✓ Added SYNC MASTER.
- ✓ Added PEAK LIMITER.
- ✓ Changed OSCILLATOR1-4 of SIDECHAIN REMIX to NOISE, HI-HAT, CLAP and SNARE.
- ✓ Improved SIDECHAIN REMIX usability in SAMPLER, PITCH and GATE.
- ✓ Added manual effects to SIDECHAIN REMIX.
- ✓ Manual effects mean that when touching the pad, effects are triggered in this version, whereas increased volume level triggered the effects in the previous version.

Ver.2.01 (19 July, 2011 Update)

- ✓ Improved BEAT EFFECT accuracy with the addition of the QUANTIZE function.
- ✓ Updated "REVERB" function for dynamic song arrangement.
- ✓ Broadened "NOISE" and "SIDECHAIN REMIX" adjustment range to increase the volume of "NOISE" and "SIDECHAIN REMIX" that you can mix into your songs.
- ✓ Updated "FILTER" function for quick effect performance.

- ✓ Software version display.

Ver.1.28 (20 August, 2010 Update)

- ✓ Decreased S/PDIF Digital Audio output level by -5dB to match Pioneer's other digital mixers.

Ver.1.27 (30 June, 2010 Update)

- ✓ ECHO function is improved to allow Feedback Loop.
- ✓ Applicable Link Monitor function of rekordbox.
- ✓ Improved stability when powered up.
- ✓ Improved other functions.