



Windows Firmware for DJM-2000NXS – CHANGE HISTORY

Ver.3.21 (10 July, 2018 Update)

[FIXED]

- ✓ Unable to record audio when using macOS10.13.2.

Ver.3.20 (16 October, 2013 Update)

- ✓ Supports "KUVO".

Ver.3.19 (30 May, 2013 Update)

- ✓ Fixed an issue where a buzzing noise may be heard when switching sampling rates on a DJ application while the USB soundcard of DJM-2000NXS is used.

Ver.3.18 (20 December, 2012 Update)

- ✓ Improved SIDECHAIN REMIX usability in SAMPLER, PITCH and GATE.
- ✓ Added manual effects to SIDECHAIN REMIX.
Manual effects mean that when touching the pad, effects are triggered in this version, whereas increased volume level triggered the effects in the previous version.