



## **Mac Firmware for DJM-250MK2 – CHANGE HISTORY**

**ver. 1.07 (14 October, 2021 Update)**

**[FIXED]**

- ✓ Occasionally unable to output DVS timecode signals when using TRAKTOR.

**ver. 1.06 (6 February, 2018 Update)**

**[IMPROVED]**

- ✓ Volume curve of the MIC LEVEL control.

**ver. 1.05 (8 August, 2017 Update)**

**[IMPROVED]**

- ✓ Cut lag length improved for a more responsive scratch performance.

**[FIXED]**

- ✓ Popping noise occurred via USB audio (FX SEND/RETURN) when switching FX assign on rekordbox with BEAT FX enabled.