



## **Mac Firmware for DJM-S9 – CHANGE HISTORY**

### **Ver.1.05 (23 November, 2015 Update)**

- ✓ IMPROVED - Cut lag length changed to 1 mm when the DJM-S9 is not connected to a computer.

### **Ver.1.04 (28 October, 2015 Update)**

- ✓ Fixed an issue where the CLIP LED was not lit.
- ✓ Fixed an issue where AUX audio is not output when FADER SYNTH is selected from BEAT FX.
- ✓ Fixed an issue where NOISE effect may not be activated when it is switched from other effect of FILTER FX in the Setting Utilities.
- ✓ Fixed an issue where the UTILITY LED remains lit even after exiting the Utility mode.
- ✓ Improved the response when the effect lever is pulled down repeatedly.
- ✓ The audio level of SAMPLER is now at an appropriate level.
- ✓ Fixed other minor issues.