

## **Firmware for DJM-V10-LF - Change History**

### **ver. 1.16 (May 14, 2025 update)**

#### **[FIXED]**

- ✓ UASP-compatible USB storage devices could not be recognized.  
NOTE: Please use a non-UASP USB storage drive to apply this update. UASP-compatible USB storage devices can be used after this update.

### **ver. 1.14 (October 17, 2024 update)**

#### **[FIXED]**

- ✓ Minor issues have been fixed.

### **ver. 1.13 (July 18, 2024 update)**

#### **[IMPROVED]**

- ✓ Following the Ecodesign Directive (Directive 2009/125/EC) of the European Union, the time needed for the unit to automatically switch off has been changed to 20 minutes when the Power Management function is turned on.  
Please note:
  - The name of the energy-saving function, (previously called Auto Standby or Auto Power-Off, depending on the model), has now been changed to Power Management.
  - To learn more about the Power Management function, see the latest Instruction Manual, which is available online.

### **ver. 1.12 (15 December, 2022 Update)**

#### **[IMPROVED]**

- ✓ Potential audio cut-out issue when connecting the DJM-V10-LF to the CDJ-3000 via PRO DJ LINK network.

### **ver. 1.11 (18 November, 2021 Update)**

#### **[FIXED]**

- ✓ Minor issues.

### **ver. 1.08 (27 April, 2021 Update)**

#### **[NEW]**

- ✓ Track titles and artist names will be automatically added to DJM-REC recordings when music is played on a CDJ-3000 in the PRO DJ LINK network.  
  
Note: Be sure to update the CDJ-3000 firmware and DJM-REC app to the latest versions.