Pioneer Dj

Firmware for DJM-V10 - Change History

ver. 1.14 (October 17, 2024 update)

[FIXED]

Minor issues have been fixed.

ver. 1.13 (July 18, 2024 update) [IMPROVED]

✓ Following the Ecodesign Directive (Directive 2009/125/EC) of the European Union, the time needed for the unit to automatically switch off has been changed to 20 minutes when the Power Management function is turned on.

Please note:

- The name of the energy-saving function, (previously called Auto Standby or Auto Power-Off, depending on the model), has now been changed to Power Management.
- To learn more about the Power Management function, see the latest Instruction Manual, which is available online.

ver. 1.12 (15 December, 2022 Update)

[IMPROVED]

✓ Potential audio cut-out issue when connecting the DJM-V10 to the CDJ-3000 via PRO DJ LINK network.

ver. 1.11 (18 November, 2021 Update)

[FIXED]

✓ Minor issues.

ver. 1.08 (27 April, 2021 Update)

[NEW]

 Track titles and artist names will be automatically added to DJM-REC recordings when music is played on a CDJ-3000 in the PRO DJ LINK network.

Note: Be sure to update the CDJ-3000 firmware and DJM-REC app to the latest versions.

ver. 1.07 (29 September, 2020 Update)

[FIXED]

 Incorrect output of MIDI messages when operated in a certain manner.

ver. 1.05 (26 March, 2020 Update)

[FIXED]

✓ Minor issues.

ver. 1.04 (4 February, 2020 Update)

[FIXED]

✓ Audio would sometimes fail to input to a channel.