



Firmware for DJS-1000 - CHANGE HISTORY

Ver.1.12 (21 January, 2020 Update)

[FIXED]

- ✓ Minor issues on the touch display.

Ver.1.11 (19 June, 2018 Update)

[FIXED]

- ✓ Sample playback sometimes distorted when using an external device as a MIDI master clock in LIVE SAMPLING mode.

Ver.1.10 (14 February, 2018 Update)

[NEW]

- ✓ Adjust the volume of multiple tracks at the same time by holding down SHIFT and selecting the tracks on the touch screen.
- ✓ Load project files from the DJS-TSP Project Creator application onto the DJS-1000*.

* Please update the DJS-1000 firmware to version 1.10 or later. You'll also need DJS-TSP Project Creator version 1.1.0 or later.

[IMPROVED]

- ✓ Maximum sample length has been extended to 64 seconds.
- ✓ Level meter for tracks live and muted.
- ✓ FX engaged icon added to the HOME screen.
- ✓ Sub parameters can be reset to default by long holding the PERFORMANCE FX, effect icon.
- ✓ Copy the original pattern when the pattern length is extended.

Ver.1.03 (19 October, 2017 Update)

[FIXED]

- ✓ Potential freeze when repeating manual LIVE SAMPLING with the beat length selected in REC LENGTH when BEAT SYNC is enabled.

[IMPROVED]

- ✓ Improved the launching process when turning on the power.