

Firmware for DVJ-1000 - CHANGE HISTORY

Ver.1.50 (10 January, 2007 Update)

✓ Improved behavior stability when the DVJ player is connected with the video switcher-VSW-1.

Ver.1.40 (13 November, 2006 Update)

✓ Improved Disc Readability
The readability of dirty and damaged discs has been improved.
Products using System Version 1.30 or earlier may have problems playing dirty or damaged discs. We recommend this update for customers currently using this product with System Version 1.30 or earlier.

NOTE: This update does not unsure playback of all dirty or damaged discs. For best results, be sure to keep your discs clean and damage-free.

✓ Improved Sound Quality with Master Tempo Sound quality has been improved during playback of discs when the Master Tempo feature is set to 'On'.