



Firmware for XDJ-700 – CHANGE HISTORY

Ver.1.13 (19 October, 2017 Update)

[FIXED]

- ✓ Track playback speed sometimes did not return to the BPM displayed on the screen when Sync is enabled.
- ✓ A popping noise occurred during a LOOP with QUANTIZE and MASTER TEMPO enabled.
- ✓ A HOT CUE started after jumping to the LOOP-IN point when changing a LOOP BEAT LENGTH with QUANTIZE enabled.

Ver.1.12 (25 April, 2017 Update)

[FIXED]

- ✓ SEARCH worked incorrectly under certain conditions.

Ver.1.11 (7 March, 2017 Update)

[FIXED]

- ✓ Search results did not appear when moving cursor during SEARCH.
- ✓ Fixed certain issues during playback and track selection.
- ✓ Information such as categories and tracks was not shown in the browser screen when a database had many tracks.

Ver.1.10 (10 November, 2016 Update)

[NEW]

- ✓ MASTER PLAYER SELECT (AUTO) support (TORAIZ SP-16 PRO DJ LINK feature)
- ✓ Search using multiple words by adding a space in the [SEARCH] category.

[FIXED]

- ✓ When connected via Pro DJ LINK, some features of the CDJ-2000NXS2 or XDJ-1000MK2 were disabled.
- ✓ Playback of an AIFF music file (24bit/48kHz) stopped and tracks could not be loaded to a deck.
- ✓ Digitally distorted white noise occurred when playing certain .WAV files.

- ✓ Artwork was changed in the BROWSE screen in some cases.
- ✓ Active loop activated a very short loop.
- ✓ Fixed problems in the Control Mode.