



Mac OS X El Capitan Driver for DDJ-RZ – CHANGE HISTORY

Ver.1.1.1 (27 January, 2016 Release)

[FIXED]

- ✓ A freeze occurred when Control Tone was selected for the Audio Output in the CONTROLLER OUTPUT tab of the Setting Utility.

Ver.1.1.0 (18 November, 2015 Release)

- ✓ Driver software for Mac OS X v10.11.1 has been released.

[FIXED]

- No audio outputted when connected to Mac OS X v10.11.1.