



Windows Driver for DDJ-T1 – CHANGE HISTORY

Ver.1.200 (6 September, 2016 Update)

[NEW]

- ✓ Support for 64-bit version of Windows 10 / 8.1 / 7.

Ver.1.100 (21 November, 2011 Update)

- ✓ Ver.1.100 supports DDJ-ERGO-V.
- ✓ Three models, DDJ-T1/DDJ-S1/DDJ-ERGO-V are supported by this driver software.

Ver.1.001 (7 March, 2011 Update)

- ✓ Added "Kernel buffer size utility" on ASIO setting utility. A sufficiently large buffer size decreases the chance of sound dropout (sound interruption) but increases audio signal transmission delay (latency). The default setting is "3" but please adjust it to "2" if you don't have any problem in current setting.