



Windows Driver for DJM-900NXS – CHANGE HISTORY

ver. 1.800 (28 July, 2020 Update)

[FIXED]

- ✓ Improved stability and fixes for other minor issues.

[NEW]

- ✓ Integrated driver installers for Windows 10 and 8.1.

ver. 1.710 (29 November, 2016 Release)

[FIXED]

- ✓ DJ applications running on certain versions of Windows 10 did not detect Pioneer DJ equipment.