

DJM-V10-LF Audio Driver for Windows – CHANGE HISTORY

ver. 1.020 (1 June, 2021 Update) [FIXED]

> ✓ Incorrect audio output from browsers and apps to the DJM-V10-LF when the mixer is selected as the output device in the Windows sound settings.

ver. 1.010 (24 November, 2020 Release)

✓ Driver software of DJM-V10-LF has been released.