



Firmware for DDJ-SB – CHANGE HISTORY

Ver.1.06 (3 August, 2015 Update)

Rare issue fixed where the DDJ-SB may freeze when paused after a number of hours.

Ver.1.05 (19 June, 2014 Update)

Fixed an issue when using Serato DJ Ver 1.6.1, where the Vinyl indicator does not change upon the Vinyl mode switch when SLIP mode is active.

Ver.1.04 (28 November, 2013 Update)

Fixed Channel Fader Start issue and SLIP mode issue with Serato DJ.