



Windows Firmware for DDJ-SZ – CHANGE HISTORY

Ver. 1.21 (21 September, 2017 Update)

[IMPROVED]

- ✓ Accuracy of the tempo slider.

[FIXED]

- ✓ Needle Search did not work on rare occasions.

Ver. 1.20 (15 December, 2014 Update)

- ✓ Fixed a MIDI conflict issue where the same MIDI code was output when selecting TALKOVER on the MIC switch as well as pressing the SHIFT button and the BROWSE knob on DECK 1.

Ver. 1.18 (23 June, 2014 Update)

- ✓ TRAKTOR PRO2 from Native Instruments is supported.
- ✓ Fixed a rare issue where the Master audio output level decreases.
- ✓ Fixed other minor issues.

Ver.1.15 (20 May, 2014 Update)

- ✓ The jog platter latency for scratching is improved.

Ver.1.12 (3 March, 2014 Update)

- ✓ Fixed an issue where Serato DJ controller mode and general MIDI controller mode were not automatically switched.
- ✓ Fixed an issue where lowering the sampler volume level to zero was not available when a PAD is pressed and released during sampler velocity mode with After touch enabled.
- ✓ Fixed an issue where the effect sound was not output from the sound card even though a SOUND COLOR FX button is selected for MIC input.