



DJM-250MK2 firmware for Windows – change history

ver. 1.08 (July 18, 2024 update)

[IMPROVED]

- ✓ Following the Ecodesign Directive (Directive 2009/125/EC) of the European Union, the time needed for the unit to automatically switch off has been changed to 20 minutes when the Power Management function is turned on.

Please note:

- The name of the energy-saving function, (previously called Auto Standby or Auto Power-Off, depending on the model), has now been changed to Power Management.
- To learn more about the Power Management function, see the latest Instruction Manual, which is available online.

ver. 1.07 (October 14, 2021 update)

[FIXED]

- ✓ Occasionally unable to output DVS timecode signals when using TRAKTOR.

ver. 1.06 (February 6, 2018 update)

[IMPROVED]

- ✓ Volume curve of the MIC LEVEL control.

ver. 1.05 (August 8, 2017 update)

[IMPROVED]

- ✓ Cut lag length improved for a more responsive scratch performance.

[FIXED]

- ✓ Popping noise occurred via USB audio (FX SEND/RETURN) when switching FX assign on rekordbox with BEAT FX enabled.