



Firmware for DJM-450 – CHANGE HISTORY

Ver.1.04 (6 February, 2018 Release)

[IMPROVED]

- ✓ Volume curve of the MIC LEVEL control.

Ver.1.03 (8 August, 2017 Release)

[IMPROVED]

- ✓ Cut lag length changed for more responsive scratch performance.
- ✓ Selected channel is shown on the display when switching the effect channel.

[FIXED]

- ✓ Popping noise occurred in USB audio (FX SEND/RETURN) when switching FX assign on rekordbox with BEAT FX enabled.
- ✓ Fixed other minor issues.

Ver.1.02 (28 February, 2017 Release)

[NEW]

- ✓ Mixer input channels are selectable when playing tracks on an application not supporting multichannel output.
Input channels are selectable on the MIXER INPUT tab in the setting utility.
To use this function, please update the driver software to the latest version.

DRIVER FOR WINDOWS: Ver.1.102 or higher

DRIVER FOR MAC YOSEMITE: Ver.1.1.2 or higher

DRIVER FOR MAC SIERRA AND EL CAPITAN: Ver.2.1.2 or higher

- * When using rekordbox and other applications supporting multichannel output, the selection is disabled. Select the channel on your application.

[FIXED]

- ✓ More precise cut lag value on both edges of the crossfader.

- ✓ Small popping noise occurred when turning the EQ/ISO knob when ISOLATOR was selected for EQ CURVE.