



## **Windows Firmware for DJM-S9 – CHANGE HISTORY**

### **Ver.1.08 (12 September, 2017 Update)**

#### **[NEW]**

- ✓ Support for rekordbox dj Ver 5.0.

#### **[FIXED]**

- ✓ While launching SeratoDJ, "Please connect SeratoDJ" was shown on rare occasions.

### **Ver.1.07 (26 July, 2016 Update)**

#### **[FIXED]**

- ✓ Windows only: PADs or PAD illumination sometimes worked incorrectly.
- ✓ Beginning of audio was cut off when it was input from AUX.
- ✓ When connecting 2 computers at the same time, recording of the master mix out was incorrect on the computer connected to a USB-B terminal.

### **Ver.1.06 (21 December, 2015 Update)**

#### **[FIXED]**

- ✓ Incorrect MIDI value when using crossfader.
- ✓ Pressing PADs repeatedly in FX TRIGGER MODE with effect lever held in LOCK leaked original sound.
- ✓ BPM of channel 1/2 BEAT FX was sometimes different from the displayed BPM with SAMPLER FX or AUX FX engaged.
- ✓ Other minor issues.

### **Ver.1.05 (23 November, 2015 Update)**

- ✓ IMPROVED - Cut lag length changed to 1 mm when the DJM-S9 is not connected to a computer.

### **Ver.1.04 (28 October, 2015 Update)**

- ✓ Fixed an issue where the CLIP LED was not lit.

- ✓ Fixed an issue where AUX audio is not output when FADER SYNTH is selected from BEAT FX.
- ✓ Fixed an issue where NOISE effect may not be activated when it is switched from other effect of FILTER FX in the Setting Utilities.
- ✓ Fixed an issue where the UTILITY LED remains lit even after exiting the Utility mode.
- ✓ Improved the response when the effect lever is pulled down repeatedly.
- ✓ The audio level of SAMPLER is now at an appropriate level.
- ✓ Fixed other minor issues.